Lower Owens River Project Flow Report for 08/12/2021

Augmenting Flows			Owens River Flows		
LORP Measuring Station	Daily	15 Day	Daily	15 Day	# Days of
LOIN Measuring Station	Avg	Avg	Avg	Avg	last 15
	Flow(cfs)	Flow(cfs)	Flow(cfs)	Flow(cfs)	at 40+ cfs
Below River Intake			76	75	15
Blackrock Ditch Return (augmentation)	1	1	İ		
Goose Lake Return (return flow)	0	0	1		
Billy Lake Return (augmentation)	1	1	1		
Mazourka Canyon Road			64	60	15
Locust Ditch Return (augmentation)	0	0	•		
Georges Ditch Return (augmentation)	0	0	İ		
Reinhackle Springs			50	57	15
Alabama Gates Return (augmentation)	0	0	İ		
At Pumpback Station ¹			46	50	15
Pump Station			43	46	
Langemann Gate to Delta			3	4	
Weir to Delta			0	0	
LORP In Channel Average Flow ²			59	60	

Pump Station Month-to-Date Average Flow 46 cfs

Blackrock Waterfowl Habitat Area									
Flooded Unit	Area	Last Collected		Flow Rate	Flow Set Date				
Thibaut	17 Acres	12/16/2020		0 cfs	04/16/2020				
Winterton	170 Acres	01/15/2021		0 cfs	04/16/2021				
Drew	243 Acres	01/12/2021		0 cfs	04/16/2021				
Waggoner	0 Acres	05/31/2011		0 cfs	04/15/2011				
Total Flooded Area	430 Acres								
Off-River Lakes and Ponds Upper Twin Lake Gage Read Lower Twin Lake Gage Read Goose Lake Gage Read Thibaut Pond Flooded Area		2.44 ft 2.25 ft 2.50 ft 28 Acres	(Last Collected: 08/11/2021) (Last Collected: 12/16/2020)						

^{1.} Above Pump Station not constructed, the flow is the sum of the Pump station discharge, the Langemann Gate releases to the delta, and flow over the spillway weir to the delta.

Note - All Data shown in this report is from field electronic measuring and data collection devices.

Note - Data contained herein is preliminary and subject to change. Refer to the disclaimer:

http://wsoweb.ladwp.com/Aqueduct/realtime/disclaimer.htm

^{2.} Average of the LORP Intake, Mazourka Canyon, Reinhackle Springs, and At Pumpback Station stations.